


| | | |
|---|--|--|
| Title: Dryer Replacement – Pneumatic-System | | |
| AG-SB-2022-02-C-EN | Effective Date: 22.09.2022 | Compliance Category: A – MANDATORY B – RECOMMENDED C - OPTIONAL |
| Applicability | | |
| Aircraft type & model: MT-03, MTOclassic, MTOsport 2017, Calidus & Cavalon | Affected Serial number(s): All models, all engine types | |
| The maintenance manual to be referenced is this stated or subsequent issue. | | As per AutoGyro website |
| This form is the response from AutoGyro GmbH either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. For help, contact airworthiness@auto-gyro.com . | | |

Documentation (Service Bulletin Completion action)

The accomplishment of this Service Bulletin, or the decision of its rejection, must be properly documented, if such procedure is required by the relevant authority

Category Codes

- A – Mandatory – failure to comply result in a significant reduction of flight safety, injury or death
- B – Recommended – failure to comply may result in reduced safety margin, injury and/or equipment damage
- C - Optional – improves operating behavior, reliability and/or maintainability

| | |
|--|--|
| Chief Certification Officer  Gerald Speich | Chief Technical Officer 21 / 09 / 2022 |
|--|--|

| | |
|--|--|
| Contact & Info: airworthiness@auto-gyro.com www.auto-gyro.com | AutoGyro GmbH Dornierstr. 14 31137 Hildesheim |
|--|--|

Reason and overview of the Service Bulletin (cause of problem if known)

The dryer design has been revised to improve aircraft serviceability; by reducing the time taken to change the dryer, and reducing the chance of introducing air leaks during the change.

Manpower estimates

There are no manpower estimates associated with this SB.
The replacement is encompassed within the maintenance requirement.

Compliance

There are no compliance requirements associated with this SB.

Customer Support

Not applicable

Tooling required

Standard tools

Weight and Balance Effects

Nil

Manuals affected

POH & AMM AutoGyro is not affected.

Previous Modifications that affect the SB

None

Accomplishment instructions (Action required to implement this bulletin):

Instructions

All work is to be carried out in accordance with the latest model-relevant AutoGyro Aircraft Maintenance Manual.

Aircraft Maintenance Manual Part E Chapter 36-21-00 8-1

Illustrations

Old Part:
20979 Dryer



New Part:
48519 Dryer II



Any life-limit changes must be recorded within the aircraft documentation, in line with the requirements of the country of operation.

Not applicable

Material information (Parts required to be made to implement this service bulletin):

Nil

List of components (with purchasable part numbers)

48519 Dryer II

Interchangeability

Not affected

Parts disposition

- a) Disposal requirements – Nil
- b) Environmental hazards of parts containing hazardous materials – Nil
- c) Scrap requirements (e.g. mutilate scrapped items beyond use) – Nil